



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Camden PERMIT NO.: SLAS-15-02 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 11-20-12

Date of Previous Inspection: 7-23-12

FACILITY NAME AND ADDRESS:

Albemarle Septic Services
 134 Belcross Rd
 Camden, NC 27921

GPS COORDINATES: N: 36.3711° W: -76.1732°

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Joseph Russell
 Telephone: 252-202-9969
 Email address:
 Fax:

FACILITY CONTACT ADDRESS:

Same

PARTICIPANTS:

Will Burke, Environmental Senior Specialist

STATUS OF PERMIT:

PURPOSE OF SITE VISIT:

Routine, Audit

OBSERVED VIOLATIONS

1.n/a

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Field border markers were up and easy to identify
2. Suggest that Winter Crop be drilled earlier in the season to promote early growth.
3. No serious odors or vectors were noted during this inspection
4. The access road was in good shape, THANK YOU.
5. Appropriate signage was up and easy to read.
6. Applications appear to have been performed in a profession and responsible manner.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (910) 796-7397

Will Burke
Regional Representative

Sent on: 12-21-12		Email		Hand delivery		US Mail		Certified No. []
-------------------	--	-------	--	---------------	--	---------	--	-------------------