



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: Onslow</b> <b>PERMIT NO.: SLAS-67-09</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection: 10-10-12**

**Date of Last Inspection: 6-12-12**

**FACILITY NAME AND ADDRESS:**

TOI of North Carolina  
 PO Box 926  
 Jacksonville NC, 28540

**GPS COORDINATES: N: 34.83714° E: -77.50041°**

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Tom Balker  
 Telephone: 910-347-2424  
 Email address:  
 Fax:

**FACILITY CONTACT ADDRESS:**

Same

**PARTICIPANTS:**

Will Burke, Environmental Senior Specialist

**STATUS OF PERMIT:**

**Active** Expires:9-28-13

**PURPOSE OF SITE VISIT:**

Routine, Audit

**OBSERVED VIOLATIONS**

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

- 1) Winter crop appears to drilled. Little to no weeds present.
- 2) Markers were up and easily identified.
- 3) Appropriate signage was up and easy to read.
- 4) Access road was in good shape.
- 5) No serious odors or vectors were noted during the inspection.
- 6) Make sure all signs are visible please.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (910) 796-7397

Will Burke

***Regional Representative***

Sent on: 12-20-12		Email		Hand delivery	X	US Mail	Certified No. [ ]
-------------------	--	-------	--	---------------	---	---------	-------------------