



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: Onslow</b> <b>PERMIT NO.: SLAS-67-12</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection: 12-27-12**

**Date of Last Inspection: 9-17-12**

**FACILITY NAME AND ADDRESS:**

TNT Enterprises  
 PO Box 1005  
 Sneads Ferry NC, 28460

**GPS COORDINATES:** N: 34.55424° W: °-77.42023

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Jody Thompson  
 Telephone: 910-327-2556  
 Email Address: N/A  
 Fax: N/A

**FACILITY CONTACT ADDRESS:**

Same

**PARTICIPANTS:**

Will Burke, Environmental Senior Specialist

**STATUS OF PERMIT:**

Processing, Expires June 22, 2012

**PURPOSE OF SITE VISIT:**

Routine, Audit

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**OBSERVED VIOLATIONS**

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**ADDITIONAL COMMENTS**

1. Access road was in good shape.
2. No serious odors or vectors were present at the time of this inspection
3. Required signage was up and easy to identify.
4. Setbacks appear to be correct (not measured).
5. Bermuda crop appears strong. Needed to be cut for hay at time of inspection.
6. Winter rye crop is up and appears to be a decent stand. No signs of burns as was noted in previous inspection.

Please contact me if you have any questions or concerns regarding this inspection report.



Will Burke  
*Regional Representative*

Phone: (910) 796-7397

Sent on:1-3-12		Email		Hand delivery	<input checked="" type="checkbox"/>	US Mail		Certified No. [ ]
----------------	--	-------	--	---------------	-------------------------------------	---------	--	-------------------