



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	<b>X</b>	<b>COUNTY: Wake</b> <b>PERMIT NO.: SLAS 92-01</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF	HHW	White goods	Incineration	T&P	FIRM		
CDFL	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		

**Date of Site Inspection:** 6/25/2013

**Date of Last Inspection:** 2/26/2013

**FACILITY NAME AND ADDRESS:**

Eastside Septic Cleaning Service  
 1018 Hwy 70 West  
 Garner, NC 27529

**GPS COORDINATES:** N: 35.64836 W: -78.60078

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: B.C. Raynor  
 Telephone: (919) 772-6145  
 Email address: N/A  
 Fax: (919) 773-1501

**FACILITY CONTACT ADDRESS:**

N/A

**PARTICIPANTS:**

Connie Wylie, Tony Gallagher  
 Everett Coates

**STATUS OF PERMIT:**

Active

**PURPOSE OF SITE VISIT:**

Routine

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

- N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. The required signs are posted and it appears that the approved setbacks are being met.
2. Some erosion is occurring on the site paths, particularly the path between field 6 & fields 5A/5B.
3. The millet is becoming established on fields 5B, 6A & 6B & the fescue appears adequate on fields 5A & 6C.
4. Field markers appear adequate and no odors were noted. No sign of recent application.

Please contact me if you have any questions or concerns regarding this inspection report.

*Connie S. Wylie*

\_\_\_\_\_  
Connie S. Wylie  
**Regional Representative**

Phone: (910) 433-3352

<b>Sent on:</b>		Email		Hand delivery	<b>X</b>	US Mail		Certified No. [ ]
-----------------	--	-------	--	---------------	----------	---------	--	-------------------