



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:										COUNTY: BUNCOMBE PERMIT NO.: 11-09 SWC FILE TYPE: COMPLIANCE	
Lined MSWLF		LCID		YW	<input checked="" type="checkbox"/>	Transfer		Compost	<input checked="" type="checkbox"/>		SLAS
Closed MSWLF		HHW		White goods		Incin		T&P	<input checked="" type="checkbox"/>		FIRM
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

Date of Site Inspection: 1/21/14

Date of Last Inspection: 5/6/13

FACILITY NAME AND ADDRESS:

Henson's Inc. Mulch & More
 116 Pond Road
 Asheville, NC 28806

GPS COORDINATES: N: 35.54434 E: -82.60630

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Ellis Fincher, Owner
 Telephone: (828) 859-5836
 Cell: (864) 270-8704
 Email address: efincher@hensonsinc.net

FACILITY CONTACT ADDRESS:

Henson's Inc.
 P.O. Box 1060
 Tryon, NC 28782
 (828) 665-0200

PARTICIPANTS:

Andrea Keller, DENR – Solid Waste Section
 Jimmy Rigsby, Site Operator

STATUS OF PERMIT:

Large Type I Compost Facility PTO: August 12, 2011
 Permit Expiration: August 12, 2016

PURPOSE OF SITE VISIT:

Comprehensive inspection

STATUS OF PAST NOTED VIOLATIONS: None

OBSERVED VIOLATIONS: None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. On site on January 21, 2014. Weather: overcast, dry, 40° F.
2. Sediment basins and erosion control measures at the facility appeared to be maintained and functional. Access roads were in good condition and site access was controlled. Surface water appeared to be diverted away from the operational, curing, and storage areas.
3. The facility is approved to accept land clearing debris, wood pallets, and yard trash. Facility operational capacity is limited to 300,000 cy (or 75,000 tons) of feedstocks received for composting per year. No unacceptable waste streams were noted at the time of the inspection.
4. Mulched materials were maintained in windrows with access lanes for fire control and it appeared that the un-ground land clearing material had adequate fire control access at the time of the inspection.



1/21/14

5. Temperature records for the 2012-2013 cy cycle (as submitted for the Facility Annual Report) were reviewed and appeared to be in compliance with the Type I material management requirements.
6. Minimal dust, windblown waste, or odors were noted at the facility at the time of inspection. In general, the facility was well-maintained and operated.

Please contact me if you have any questions or concerns regarding this inspection report.



Andrea Keller
Environmental Senior Specialist
Regional Representative

Phone: 828-296-4700

Sent on: January 22, 2014		Email: efincher@hensonsinc.net	Mail: Henson's Inc. Mulch & More 116 Pond Road Asheville, NC 28806
----------------------------------	--	---	---

ec: Tony Gallagher, Compost & Land Application Branch Manager
Jason Watkins, Western District Supervisor – Solid Waste Section
Sarah Rice, Compliance Officer – SWS
Liz Patterson, Compost & Land Application Branch - SWS