



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS		<b>COUNTY: Cherokee</b> <b>PERMIT NO.: 20-01</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF	<b>X</b>	HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** October 27, 2011 **Date of Last Inspection:** November 25, 2008

**FACILITY NAME AND ADDRESS:**

Old Cherokee County MSW landfill  
 Fairview Road (NC Hwy 1515)  
 Marble, NC 28905

**GPS COORDINATES:** N: 35.17883 E: -83.90334

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Jeff Clark, Cherokee Co. Solid Waste Director  
 Telephone: 828-837-2621  
 Email address: jeff.clark@cherokeecounty-nc.gov  
 Fax: 828-837-4669

**FACILITY CONTACT ADDRESS:**

Cherokee County Solid Waste Department  
 c/o Cherokee County Courthouse  
 75 Peachtree Street  
 Murphy, NC 28906

**PARTICIPANTS:**

Troy Harrison, NC DENR-DWM Solid Waste Section  
 Jeff Clark, Landfill Manager, Cherokee County

**STATUS OF PERMIT:**

Landfill Closed  
 Waste last received on 12/31/97

**PURPOSE OF SITE VISIT:**

Comprehensive Audit of Closed Landfill

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

N/A

**ADDITIONAL COMMENTS**


1. Landfill operations ceased in December 31, 1997. All waste has been taken, after that date, to the new landfill (Permit No. 20-02).

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

2. Vegetation was well established on top of the landfill. The grass had been recently mowed. No evidence of leachate breakouts were observed.
3. The ground water monitoring wells were observed. All of the wells were visually observed as locked and in good condition. The landfill gas wells were also observed in good condition. All wells are inspected regularly according to Mr. Clark. Landfill gas is collected and directed to a flare.
4. No low areas or ponded water on the cap were observed.
5. Access to the landfill is restricted by a locked gate.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 828-296-4701

Environmental Senior Specialist  
***Regional Representative***

Sent on: <b>October 28, 2011</b>	X	Email		Hand delivery		US Mail		Certified No. [ ]
----------------------------------	---	-------	--	---------------	--	---------	--	-------------------

Copies: Jason Watkins, District Supervisor  
Shawn McKee, Compliance Officer