



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS	COUNTY: Cumberland PERMIT NO.: 26L-LCID FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

Date of Site Inspection: March 25, 2014 **Date of Last Inspection:** January 31, 2012

FACILITY NAME AND ADDRESS:

Snow Hill LCID Landfill, Claude Lee Road Road, Hope Mills, North Carolina 28384

GPS COORDINATES: N: 34.97193 E: -78.88698

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Frank McDonald
 Telephone: 910-630-2200
 Email address: mcdonaldf@embarqmail.com
 Fax: 910-630-2225

FACILITY CONTACT ADDRESS:

McDonald Materials Inc., 2611 Murchison Road, Fayetteville, North Carolina 28301

PARTICIPANTS:

Drew Hammonds, Solid Waste Section

STATUS OF PERMIT:

Permit to Construct and Operate issued June 30, 2010

PURPOSE OF SITE VISIT: Comprehensive Inspection

STATUS OF PAST NOTED VIOLATIONS: NA

OBSERVED VIOLATIONS

- 1. 15A NCAC 13B .0566 (3)(j):** Excavation, grading and fill material side slopes shall not exceed three to one (3:1).
- 2. 15A NCAC 13B .0566 (1):** Operational plans shall be approved and followed as specified for the facility.
- 3. 15A NCAC 13B .0566 (2):** The facility shall only accept those solid wastes which it is permitted to receive.
- 4. 15A NCAC 13B .0566 (3):** Solid Waste shall be restricted to the smallest area feasible and compacted as densely as practical into cells.
- 5. 15A NCAC 13B .0566 (4):** Adequate soil cover shall be applied monthly or when the active area reaches one acre in size, whichever occurs first.
- 6. 15A NCAC 13B .0566 (16)** states that "A sign shall be posted at the facility entrance showing the contact name and number in case of an emergency and the permit number. The permit number requirement is not applicable for facilities not requiring an individual permit."

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 3

ADDITIONAL COMMENTS.

1. This is a landfill that requires a permit, thus the sign posted at the entrance needs to be corrected in accordance to the rule.
2. It appears that the trees have been cleared for the landfill footprint. Ensure that any grading activities in this area did not reduce the separation of the fill area to the groundwater.
3. Excavation, grading and fill material side slopes shall not exceed 3:1. Vertical side slopes with exposed waste was observed at the landfill during this inspection.
4. **Solid waste shall be restricted to the smallest area feasible and compacted as densely as practical into cells.** There are two working faces at this landfill. One for yard waste and one for inert debris and asphalt.
5. **Adequate soil cover shall be applied monthly, or when the active area reaches one acre in size, whichever occurs first. The combined exposed waste was over one acre at the time of this inspection.**
6. **The disposal unit boundary must be accurately identified with permanent markers.**
7. The property lines and edge of waste should be **permanently marked and visible** to ensure that the buffer of 100' is maintained and the 13.35 acre landfill area is not exceeded.
8. The facility shall only accept those solid wastes which it is permitted to receive. Unacceptable waste (i.e.: plastic, metal and painted block) was observed in the landfill during this inspection. **All unacceptable waste must be removed and disposed of properly at a facility permitted to receive the waste. Recommend staff responsible for dumping at or operating the landfill receive training on the permit conditions and operations plan for this facility to ensure unacceptable waste is removed right away.**
9. Provisions for ground cover sufficient to restrain erosion must be accomplished within 30 working days or 120 calendar days upon completion of any phase of landfill development.
10. 120 calendar days after completion of any phase of disposal operations, or upon revocation of a permit, the disposal area shall be covered with a **minimum of one foot** of suitable soil cover sloped to allow surface water runoff in a controlled manner.
11. All exposed waste must be covered and provisions for a ground cover sufficient to restrain erosion accomplished within 30 working days.
12. **The permitting branch has not received the registered professional engineer's certification that this landfill has been constructed in accordance with the approved plans. Submit the written certification that the waste disposal unit has been constructed in accordance the permit and approved plans to Elizabeth Werner Permitting Branch (919-707-8253).**
13. **Corrective measures to bring the landfill into compliance should be completed within 30 days receipt of this report. Failure to correct the observed violations may lead to enforcement.**
14. Digital photos were taken during the audit.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 910-433-3350

Solid Waste Section
 Environmental Senior Specialist
Regional Representative

Sent on: April 14, 2014	X	Email		Hand delivery		US Mail	X	Certified No. []
-------------------------	---	-------	--	---------------	--	---------	---	-------------------

Copies: Dennis Shackelford, Eastern District Supervisor (email)
 Jessica Montie, Compliance Officer (email)
 Elizabeth Werner, Solid Waste Section Hydrogeologist (email)
 Tew Family LLC, 3732 Wilmington Hwy, Fayetteville, NC 28306 (Mail)

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section



South side facing E. Exposed waste, painted.



Painted block and metal south side slope facing SW.



Working face (YW) facing E.



Working face (YW) facing NW.



Erosion on side slopes and top of waste NE end.



Sign at gate to be corrected, needs permit number.