



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID		YW		Transfer	<input checked="" type="checkbox"/>	Compost		SLAS	<b>COUNTY:</b> Forsyth <b>PERMIT NO.:</b> 34-16T <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** July 31, 2013

**Date of Last Inspection:** May 31, 2012

**FACILITY NAME AND ADDRESS:**

Overdale Road Transfer Station  
 5000 Overdale Road  
 Winston-Salem, North Carolina 27101

**GPS COORDINATES:** **N:** 36.03323    **W:** 80.23202

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Mark Bacon, General Manager  
 Telephone: (336) 724-0842 (o) or (336) 714-4300 (m)  
 Email address: [baconm@repsrv.com](mailto:baconm@repsrv.com)  
 Fax: (336) 724-0412

**FACILITY CONTACT ADDRESS:**

Mark Bacon, General Manager  
 Republic Services of North Carolina, LLC  
 2875 Lowery Street  
 Winston-Salem, North Carolina 27107

**PARTICIPANTS:**

Mark Tabaczynski, Division Manager, Republic Services of North Carolina, LLC  
 Charles Gerstell, NCDENR-Solid Waste Section

**STATUS OF PERMIT:**

A Permit to Operate the Overdale Transfer Facility was issued to Republic Services of North Carolina, LLC (Owner & Operator) on September 17, 2012. This permit shall expire on September 17, 2017.

**PURPOSE OF SITE VISIT:**

Comprehensive Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 3

**ADDITIONAL COMMENTS**

1. The facility is owned by Republic Services of North Carolina, LLC.
2. The transfer station operation and hauling is contracted to K.R. Drenth Trucking, Inc.
3. The facility currently accepts approximately 350 tons of municipal solid waste each operating day per Mr. Tabaczynski.
4. The permit and operations plan were current and available for review upon request.
5. Waste screening reports were reviewed. Facility staff performed one waste screening each operating day as outlined in the approved operations plan. Majority of screenings were performed during the same period of the day, usually in the late afternoon. Please be sure to mix up the timing of screenings to include mornings in order to get a more random inspection of loads.
6. Transfer Station Operations Specialists:
  - Sandra G. Lucas (expires 7/15/15)
  - Franklin May (expires 4/14/12)
  - Ronnie McIntyre (expires 10/20/14)
  - Jacquelyn N. Posey (expires 6/3/14)
  - Joseph E. Prestandrea (expires 4/5/14)
  - Larry L. Sansbury (expires 12/14/14)
  - Sylvester E. Scales (expires 6/3/14)
  - Mark Tabaczynski (expires 1/1/15)
7. The facility had proper signage.
8. A gate was provided at the entrance to the facility to prevent unauthorized access when the facility is not in operation.
9. Four tires were observed within a load of waste which had recently been delivered to the transfer station. Mr. Tabaczynski approached facility staff and had the tires removed from the waste stream and set aside for placement in the tire container prior to the end of the inspection. Please continue efforts to remove unacceptable waste streams as they are observed. Your attention to this matter is appreciated.
10. Rebar has been exposed within the tipping floor at the northeast corner of the facility adjacent to the trailer loading area as noted on the previous inspection report. Some of the rebar was completely undermined which could leave it susceptible to being hit by facility equipment. It is recommended that steps be taken to repair this area and any additional damaged areas to prevent further degradation of the concrete floor.
11. The walls of the transfer facility were free from heavy buildup of residue at the time of inspection. Walls had been recently pressure washed.
12. A significant amount of waste was located on the floor of the transfer trailer loading bay and on top of the structural beams along the wall in the loading bay during the inspection. Please ensure that all waste in these areas is picked up and properly disposed of at the end of each operating day. Mr. Tabaczynski stated that waste in these areas is picked up at the end of the working day.
13. Fire extinguishers were available in case of fires at the facility. All observed were found to have a full charge.
14. Windblown waste was well controlled at the time of inspection.
15. Bait boxes were installed along the perimeter of the facility for vector control. One bait box had been displaced on the north side of the transfer station. This device should be placed back in its designated area.
16. During the inspection, a buildup of small pieces of waste consisting primarily of paper and glass was observed on the exterior side of the east wall adjacent to the trailer loading area. This waste must be picked up and returned to the transfer station. Mr. Tabaczynski stated that he would have staff remove the material. It is recommended that this area be investigated to see how waste is breaking through the wall and see if repairs are needed.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (704) 235-2144

\_\_\_\_\_  
Charles T. Gerstell  
Environmental Senior Specialist  
***Regional Representative***

Sent on: <u>8/6/13</u>	<input checked="" type="checkbox"/>	Email		Hand delivery		US Mail		Certified No. <u>  </u>
------------------------	-------------------------------------	-------	--	---------------	--	---------	--	-------------------------

Copies: Jason Watkins, Western District Supervisor  
Sarah M. Rice, Compliance Officer  
Mark Tabaczynski, District Manager, Republic Services of North Carolina, LLC