



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID Notification	X	YW	Transfer	Compost	SLAS	COUNTY: Carteret NOTIFICATION NO.: N0218 FILE TYPE: COMPLIANCE
Closed MSWLF	HHW		White goods	Incin	T&P	FIRM	
CDFL	Tire T&P / Collection		Tire Monofill	Industrial Landfill	DEMO	SDTF	

Date of Site Inspection: 08 January 2014 **Date of Last Inspection:** 19 June 2013

FACILITY NAME AND ADDRESS:

Larry Styron LCID Landfill
Herring-Smith Road
Newport, NC 28570

GPS COORDINATES: N: 34.76937 E: 76.84432

FACILITY CONTACT NAME AND PHONE NUMBER:

Tina Sibley
252.422.8404

FACILITY CONTACT ADDRESS:

Styron Properties
PO Box 1599
Morehead City, NC 28570
E-mail: tsibley@ec.rr.com

PARTICIPANTS:

Ray Williams; NCDENR-Solid Waste

STATUS OF PERMIT:

Active: Landclearing and Inert Debris (LCID) Landfill Notification for a site less than 2 acres in size.

PURPOSE OF SITE VISIT:

Comprehensive Facility Compliance Inspection

STATUS OF PAST NOTED VIOLATIONS:

None applicable

OBSERVED VIOLATIONS:

No violations were observed during this Facility Compliance Inspection. Please see ADDITIONAL COMMENTS section below.

ADDITIONAL COMMENTS:

- 1) This Facility is a Land-Clearing and Inert Debris (LCID) Landfill Notification.
- 2) This Facility is recorded with the Carteret County Register of Deeds at: Book 913; Page 399.
- 3) This Facility is permitted to receive for disposal:
 - a. Land Clearing Waste: stumps, trees, limbs, brush, grass, and other naturally occurring vegetative materials generated solely from land clearing activities.
 - b. Yard Trash: brush, grass, tree limbs, and similar vegetative materials resulting from landscaping and yard maintenance.
 - c. Inert Debris and Untreated Wood: concrete, brick, concrete block, uncontaminated soil, gravel and rock, untreated and unpainted wood; and
 - d. Used Asphalt: used asphalt or asphalt mixed with dirt, sand, gravel, rock, and concrete.
- 4) The disposal area for this Facility may not exceed 2 acres in total size.
- 5) This Facility is monitored by a 24 hour security camera placed adjacent the facility access road.
- 6) This Facility is secured by a locked gate at the facility entrance and has controlled access for safety. The gate was closed and locked and no attendant was on site during this Facility Compliance Inspection.
- 7) It appears that ATV traffic is entering the property around the access gate on the side adjacent to the railroad right-of-way. *Measures need to be taken to prevent all unauthorized access in this area.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0218-20140108INSP

Page 2 of 2

- 8) The access road to the Facility is being managed properly at this time.
- 9) The Facility has been capped and is no longer receiving waste. However, the facility operator wishes to maintain active status for possible future use.
- 10) The Facility sign has been damaged. *Please re-post proper signage at the facility entrance stating the facility emergency contact number and types of waste accepted.
- 11) The landfill disposal footprint markers have been knocked down and/or removed. *Please re-install the landfill footprint markers to delineate the waste disposal boundaries.
- 12) A cover crop of native warm season grasses has been established throughout the facility. *Please mow the landfill cover crop and the perimeter of the landfill for more efficient Facility Inspections and maintenance operations.



- 13) Soil has been stockpiled on-site for use in cover maintenance in an area adjacent to the landfill access ramp.
- 14) *Corrective actions are required as a result of this Facility Compliance Inspection Report.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.

Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

Regional Representative

Delivered on : <u>13 January 2014</u> by	X	Electronic delivery		US Mail		Certified No. []
--	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: dennis.shackelford@ncdenr.gov
Jessica Montie; Chief Compliance Officer/SWS: Jessica.montie@ncdenr.gov

C: \2014\Carteret\Notifications\N0218\Inspections\N0218-20140108INSP
NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>

Go Green! Thank you for helping NCDENR be environmentally responsible.

One
North Carolina
Naturally