



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID Notification	<b>X</b>	YW		Transfer		Compost		SLAS	<b>COUNTY: Carteret</b> <b>NOTIFICATION NO.: N1073</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** 18 June 2014

**FACILITY NAME AND ADDRESS:**

Anna Wink LCID Landfill #2  
 Anna Wink Road  
 Newport, NC 28570

**GPS COORDINATES:** **N:** 34.780657 **E:** -076.942469

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Tina Sibley  
 252.422.8404

**FACILITY CONTACT ADDRESS:**

Styron Properties  
 PO Box 1599  
 Morehead City, NC 28570  
 E-mail: [tsibley@ec.rr.com](mailto:tsibley@ec.rr.com)

**PARTICIPANTS:**

Larry Styron; Styron Properties  
 Ray Williams; NCDENR-Solid Waste

**STATUS OF PERMIT:**

Active: Landclearing and Inert Debris (LCID) Landfill Notification

**PURPOSE OF SITE VISIT:**

Comprehensive Facility Compliance Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

None applicable

**OBSERVED VIOLATIONS:**

No violations were observed during this Facility Compliance Inspection; *please see* ADDITIONAL COMMENTS section below.

**ADDITIONAL COMMENTS:**

- 1) This facility is a Land-Clearing and Inert Debris Landfill Notification.
- 2) This facility is recorded with the Carteret County Register of Deeds at: Book 913; Page 399.
- 3) This facility is permitted to receive for disposal:
  - a. Land Clearing Waste: stumps, trees, limbs, brush, grass, and other naturally occurring vegetative materials generated solely from land clearing activities.
  - b. Yard Trash: brush, grass, tree limbs, and similar vegetative materials resulting from landscaping and yard maintenance.
  - c. Inert Debris and Untreated Wood: concrete, brick, concrete block, uncontaminated soil, gravel and rock, untreated and unpainted wood; and
  - d. Used Asphalt: used asphalt or asphalt mixed with dirt, sand, gravel, rock, and concrete.
- 4) The disposal area for this Facility may not exceed 2 acres in total size.
- 5) The access road to the Facility is being managed properly at this time.
- 6) This Facility is secured by a locked cable at the Facility entrance and has controlled access for safety.
- 7) Proper signage has not been posted at the Facility entrance. \*As per our conversation, please post proper signage at the Facility Entrance listing the Facility Emergency Contact Name and telephone number.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

N1073-20140618INSP

Page 2 of 3

- 8) The perimeter of the landfill has not been marked as required. \*Please install permanent markers around the disposal area footprint.
- 9) The perimeter road has been cleared to provide access around the toe of the landfill.
- 10) \*All landfill sideslopes need to be covered, graded, and maintained at a slope not greater than 3:1.



- 11) \*All outside slopes need to be seeded and mulched to establish a groundcover suitable to prevent erosion of your landfill cap system.
- 12) Please ensure that the active working area is covered monthly, or when the active working area reaches 1 acre in size, whichever occurs first.
- 13) Waste has been pushed from the working face over the southern sideslope. \*Please ensure that the active working area is maintained in a compact area and that the landfill is constructed using a lift-type progression. All outside slopes should be compacted and covered as soon as possible.



- 14) The waste type in the landfill was reviewed. No unpermitted wastes were observed during this Facility Compliance Inspection.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**


N1073-20140618INSP

Page 3 of 3



- 15) No off site erosion was observed during this Facility Compliance Inspection.
- 16) No violations were observed during this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.



Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: [ray.williams@ncdenr.gov](mailto:ray.williams@ncdenr.gov)

***Regional Representative***

<b>Delivered on :</b> <u>23 June 2014</u> <b>by</b>	X	Electronic delivery		US Mail		Certified No. [ ]
---	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: [dennis.shackelford@ncdenr.gov](mailto:dennis.shackelford@ncdenr.gov)  
Jessica Montie; Chief Compliance Officer/SWS: [jessica.montie@ncdenr.gov](mailto:jessica.montie@ncdenr.gov)

C: \\2014\Carteret\Notifications\N1073\Inspections\N1073-20140618INSP  
NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>

 Go Green! Thank you for helping NCDENR be environmentally responsible.

One  
North Carolina  
*Naturally*