



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID	X	YW		Transfer		Compost	SLAS		COUNTY: Wilson
Closed MSWLF		HHW		White goods		Incineration		T&P	FIRM		PERMIT NO.: N0403
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF		FILE TYPE: COMPLIANCE

Date of Site Inspection: December 17, 2013 **Date of Last Inspection:** October 14, 2013

FACILITY NAME AND ADDRESS:

L&L Landfill
 4468 London Church Rd.
 Wilson, North Carolina

GPS COORDINATES: N: 35.79740 E: 77.90734

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Johnnie Langley
 Telephone: 252 304 6149 Johnnie Langley, 252 245 0098 Ronnie Langley
 Email address: langldsc@gmail.com Ronnie Langley
 Fax: 252 281 1007

FACILITY CONTACT ADDRESS:

Johnnie Langley 3009 Anderson Rd. Wilson, North Carolina 27893	Langley's Landscaping & Lawn Care, website: langleyslandscaping.com 3010 Heard Rd Wilson, North Carolina 27896
--	---

PARTICIPANTS:

Ben Barnes NCDENR, Solid Waste Section
 Ronnie Langley, Langley's Landscaping & Lawn Care
 4472 London Church Rd. Elm City, NC 27822

STATUS OF PERMIT:

Notified site, no permit required

PURPOSE OF SITE VISIT:

Follow up inspection to discuss conditions found on site during inspection conducted on January 22, 2013

STATUS OF PAST NOTED VIOLATIONS:

NONE

OBSERVED VIOLATIONS

15A NCAC 13B .0564 SITING CRITERIA FOR LAND CLEARING AND INERT DEBRIS (LCID)

LANDFILLS The following siting criteria shall apply for Land Clearing and Inert Debris (LCID) landfills:
 (9) The facility shall meet the following minimum buffer requirements: (b) 100 feet from the disposal area to property lines, residential dwellings, commercial or public buildings, and wells. *The L&L Landfill is in violation of this rule due to the landfill now being located on two separate tracts of land with waste being located up to the property line dividing both tracts.*

15A NCAC 13B .0563 APPLICABILITY REQ. FOR LAND CLEARING/INERT DEBRIS (LCID)

LANDFILLS (2) Where an individual permit is not required, the following applies: (c) When the land on which the Land Clearing and Inert Debris Landfill is sold, leased, conveyed, or transferred in any manner, the deed or other instrument of transfer shall contain in the description section in no smaller type than that used in the body of the deed or instrument a statement that the property has been used as a Land Clearing and Inert Debris Landfill and a reference by book and page to the recordation of the notification. *The L&L Landfill is in violation of this rule in that the property containing the landfill was subdivided into two parcels. The LCID notification was not referenced in the new deed.*

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section


Page 2 of 4

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS:

1. The L&L landfill was originally located on land recorded in Book 1553 Page 913 of the Wilson Co. Register of Deeds and was a then a single tract. The tract was jointly owned by Harold Jennings Lamm Jr. and wife Jaenora Edwards Lamm and John Henry Langley and wife Patricia Walston Langley. On March 8, 2012 this same tract was divided and part of the original parcel containing L&L was transferred to Harold Jennings Lamm and wife Jaenora Edwards Lamm by general warranty deed and recorded in Book 2485 Page 763. The rest of the tract that contained the remaining part of L&L was transferred to John Henry Langley and wife Patricia Walston Langley and recorded in Book 2485 Page 760 both recorded in the Wilson Co Register of Deeds. See aerial photos below.
2. The original LCID Notification was recorded in Book 1678 Page 837 of the Wilson Co. Register of Deeds.
3. **There are several possible remedies to rectify the observed violations. These remedies are too involved to list in this inspection report. It is very important that you contact me at the number listed below to schedule a meeting for discussing these possible actions. Failure to correct these violations may result in the Division pursuing further actions.**

Please contact me if you have any questions or concerns regarding this inspection report.




Phone: 252 236 4453 email ben.barnes@ncdenr.gov

Ben Barnes
 Environmental Senior Specialist
Regional Representative

Sent on	December 31, 2013		Email		Hand delivery		US Mail	X	Certified No. 7011 2000 0001 6591 2148
By:									

Copies: Dennis Shackelford, Eastern District Supervisor
 Jessica Montie, Compliance Officer
 Harold Jennings Lamm


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section



http://gis.wilson-co.com/ConnectGIS_v6/Disclaimer.aspx

2/1/2013

Aerial of the Jennings property part of the LCID landfill and the landfill



http://gis.wilson-co.com/ConnectGIS_v6/Disclaimer.aspx

2/1/2013

Aerial of the Langley property and part of the landfill and the landfill Surface of the landfill facing northwest

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 4 of 4



Surface of the landfill facing east



Southern slope of the landfill