



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:										
Lined MSWLF		LCID	X	YW		Transfer		Compost	SLAS	COUNTY: Nash PERMIT NO.: Notified LCID no permit FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P	FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF	

Date of Site Inspection: April 3, 2013 **Date of Last Inspection:** Initial inspection

FACILITY NAME AND ADDRESS:
 Peacock Brothers Enterprises Inc. Landfill
 1583 Bend of the River Rd.
 Elm City, North Carolina 27822

GPS COORDINATES: N: 35.85490 E: 77.98557

FACILITY CONTACT NAME AND PHONE NUMBER:
 Name: Dennis and Cary Peacock
 Telephone: 252 237 5010 252 237 0775
 Email address: none
 Fax: none

FACILITY CONTACT ADDRESS:
 Dennis and Cary Peacock
 2008 Hermitage Rd.
 Wilson, North Carolina 27896

PARTICIPANTS:
 Ben Barnes, NCDENR Solid Waste
 Carrie Peacock, Peacock Bros Landfill

STATUS OF PERMIT:
 Notified site, no permit needed

PURPOSE OF SITE VISIT:
 Comprehensive inspection

STATUS OF PAST NOTED VIOLATIONS:
NONE

OBSERVED VIOLATIONS
NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 4

ADDITIONAL COMMENTS

1. The landfill is located on property owned by Dennis Peacock and Allen Thomas (a 487 acre tract parcel ID#023624) recorded in Book 881, Page 455 of the Nash Co. Register of deeds.
2. The Peacock Bro's Landfill is recorded in Book 1665 Page 1026 of the Nash Co. Register of Deeds.
3. The Peacock Bro's Enterprises Landfill is recorded in Book 1872 Page 568 of the Nash Co. Register of Deeds.
4. Entrance to the site is controlled by a gate an operator is on site at all times.
5. Ms. Peacock stated the Peacock Bro's Enterprise Landfill is receiving little waste. The Peacock Bros' Landfill is no longer being used. The DOT is doing most of the dumping and that consists of beneficial fill to be used for closure of an old hog lagoon behind the office. She stated the site may be closed, turned over to the DOT or a family member might take it over.
6. Ensure that all waste is covered monthly or when the operational area reaches one acre in size.
7. If use is to continue, the 2 acre boundary of the landfill needs to be staked.
8. The facility has been inspected several times in the past, but old inspection records could not be located.
9. **If ownership of the property changes and the new owner wishes to continue using the landfill, this notification is not transferable. A new one would need to be recorded.**
10. **If the Peacock Bro's Landfill is no longer to be used it needs be closed according to conditions listed in 15A NCAC 13B .0510 and .0566.**

Please contact me if you have any questions or concerns regarding this inspection report.

Ben Barnes

Phone: 252 236 4453 email: ben.barnes@ncdenr.gov

Ben Barnes
 Environmental Senior Specialist
Regional Representative

Sent on: April 17, 2013		Email		Hand delivery	X	US Mail		Certified No. []
-------------------------	--	-------	--	---------------	---	---------	--	-------------------

Copies: Dennis Shackelford, Eastern District Supervisor
 Jessica Montie, Compliance Officer

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 4



View of east slope of Peacock Bros Enterprises Inc

Landfill



View of eastern slope of Peacock Bros Enterprises

Inc Landfill



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 4 of 4



View of south slope of Peacock Bros Enterprises

Inc Landfill



View of Peacock Bros Landfill